
(Revised 5/97)

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple Suite 1210 Box 145801

Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	<u>Gene</u>	ral Information					
	1.	Report Time Period: From (mo./yr.) 1/97 To (mo./yr.) 12/97					
	2.	DOGM File Number (Mine No): 5 / 003 / 043					
	3.	Mine Name: GROUSE CREEK CLAY					
	4.	Mineral(s) Mined (or permitted to mine): HICH ALUMINA CLAY					
	5.	Type of mine ☐ Surface Mine or ☐ Underground Mine					
	6. Legal Description (Location of Lands Affected):						
		<u>SW</u> 1/4, <u>NE</u> 1/4, <u>1/4, Section 26</u> , Township <u>9N</u> , Range <u>19W</u>					
		1/4,1/4,1/4, Section, Township, Range					
		1/4,1/4,1/4, Section, Township, Range					
7.	Name	ne of Operator or Company: ASH GROVE CEMENT COMPANY					
	8.	Permanent Street Address: 8900 INDIAN CREEK PARKWAY					
	City, State, Zip: OVERLAND PARK, KS 66210						
		Phone: (913) 451-8900					
_	9.	Company Representative (or designated operator):					
	Name: DON KILLEBREW						
		Title: PLANT MANAGER-INKOM CEMENT PLANT					
		Business Address: 230 CEMENT ROAD					
		City, State, Zip: INKOM ID 83245					
	Phone: (208) 775-3351						
		☐ Please check if any of the above information has changed since previous year.					
II.	<u>Minii</u>	Mining and Reclamation					
	1.	Was the mine active during the past year? Yes ☒ No □					
	2.	If active, how much ore or mineral was mined? 4616 tons					
	3.	If inactive, what year was the mine last active?					

		3.	How much additional acreage wa	s disturbed during the past year? 2 acres		
		4.		onal surface disturbances that occurred during the include the type of work performed, and volume of		
			Stripped light overburden on	2 acres and stockpiled for reclamation;		
			ripped, loaded, and removed	4616 tons of clay.		
	5.		How much acreage was reclaimed dur	ing the past year? none		
	6.		Briefly describe the reclamation work p should include methods employed, and	performed during the past year. This description an evaluation of the results.		
	7.		What is the total disturbed acreage at years end? acres			
	8.	Briefly summarize any mining and/or reclamation plans for the upcoming year. Strip overburden on 2 additional acres and stockpile for				
			emove approximatelyy10,000 tons.			
NOTE	:		Section III "Additional Information" a	applies only to large mining operations.		
		n al 1				
III. <u>Aaa</u>	<u> </u>	1)	<u>information</u>			
1.			An updated surface facilities map should be attached if there have been significant changes since the prowas submitted.			
	2. Any monitoring results or other reports that are required under the terms of the approved should also be attached.					
IV. <u>Si</u>	gnat	ure	<u>Requirement</u>			
	I h	hereby certify that the foregoing is true and correct.				
			Name (Typed or Print):	Don Killebrew		
			Title of Operator:	Plant Manager-Inkom Cement Plant		
			Signature of Operator:	Don Killeliew		
			Date:	1-2-98		
,						

jb MR-AR